



During a rain, you can see the water pooled up in this KB Homes balcony that has failed. Homeowner hasn't stepped foot on this balcony in over 16 months.




4 year old building



KB Homes Protestors hit the street.



Signs of water intrusion on exterior of KB Home
Image 6 of 20 < Prev Next >



This is the wall barrier that is set up inside KB Homes Willowbrook homes to separate homeowners from the massive amount of construction work needed to totally reconstruct their balconies and alleviate water intrusion issues.



Look at the rotted wood!!! Do you want to live in this KB Home?
Image 8 of 20 < Prev Next >



Is this what KB Homes calls a repair?





KB Homes water intrusion, mildew and mold in garage from water intrusion on front of building.

Image 14 of 20 < Prev Next >



Collapsed balcony ceiling on the exterior of this KB Home

Image 11 of 20 < Prev Next >



Inside KB Homes garage, mildew on the wall from water intrusion issues.



Water damage on the interior of this KB Homes leaves homeowners scrambling for towels and restoration work.



More stucco and rotted wood removed from KB Homes Willowbrook townhomes, getting to the source of water intrusion.



Can you see the guiderail bowing in? This KB Home exterior balcony is failing
Image 17 of 20 < Prev Next >



Image 18 of 20 < Prev Next >





Water Intrusion on Exterior of KB Homes

















More stucco and rotted wood removed from KB Homes Willowbrook townhomes, getting to the source of water intrusion





KB Homes water intrusion, mildew and mold in garage from water intrusion on front of building.
Image 17 of 20 < Prev Next >







What if you came home from vacation to find that your KB Homes balcony roof had fallen down? That's what happened to this family.





KB Homes Stucco Problems at
Palm River Townhomes in
Tampa, FL.









KB Homes Exterior Balcony Failure



KB Homes Protestors hit the street.







Builder KB Homes tries to rectify water intrusion and structural damages. Homeowners deal with separation wall in bedrooms and living rooms.

Image 11 of 20 < Back Next >





KB Homes Protestors hit the street.



KB Homes Protestors hit the street.





KB Homes Protestors hit the street.



KB Homes trying to fix Wedgewood neighborhood, one of 14 KB Homes neighborhoods with problems.



KB Homes Protestors hit the street.



KB Homes Protestors hit the street.





KB Homes Protestors hit the street.

Image 48 of 200 of Daily News

